

The following issues have been fixed in SCIA Concrete Section 17.01.

Description of the issue	Ticket Number
Fixed an issue where inputted reinforcement was not accounted for in case the limit cracking force was zero.	NNLL-AM7CLD
Fixed an issue in the crack width calculation for the Dutch National Annex.	NNLL-AMDHQ5
The output table was modified so the decision column scales dynamically with the content.	
Confusing symbols in the Check status for the Interaction diagram were removed	NNLL-ALYDSK