

SCiA Concrete Section 17.1

The following issues have been fixed in SCIA Concrete Section 17.1

Description of the issue	Ticked number
The issue in the SCIA Concrete Section with the inconsistent relative axial force and correction factor for second order effect has been fixed.	NNLL-ARSLFE
The combo-box for the cross-section environment class for NBN is now visible in the SCIA Concrete Section dialog.	NNLL-AR6FQU